

spare part list



- SLD
- DLD
- ZigZag
- Speed Flow Compact
- X-Flow 90



spare part list

SD: SLD, DLD



ZZ: ZigZag

SFC: Speed Flow Compact

1.0

XF: X-Flow 90 1.0

1.0: version 1.0




1.2: version 1.2





1.5: version 1.5

| article code | description | picture | sorter type |
|--------------|---------------------------|---------|--|
| | | | SD ZZ SFC XF |
| S000093.400 | Belt drive unit 400 | | - - - ● |
| S000093.600 | Belt drive unit 600 | | - - - ● |
| V000056 | Belt, poly-V 330mm 4 ribs | | SD ZZ SFC XF 1.0- 1.0- ● - 1.2● 1.5● |
| V000076 | Belt, poly-V 483mm 4 ribs | | SD ZZ SFC XF - 1.0- - - - 1.5● |



spare part list

| | | | | | | |
|-------------|----------------------------|--|--------------------|----------------------------|----------|---------|
| V000055 | Belt, poly-V 559mm 4 ribs |  | SD 1.0- 1.2● | ZZ 1.0- 1.5● | SFC ● | XF - |
| V000028 | Belt, timing HTD 5M-265-9 |  | SD 1.0● 1.2- | ZZ 1.0● 1.2● 1.5- | SFC - | XF - |
| V000097.325 | Belt, timing HTD 5M-325-15 |  | SD - | ZZ - | SFC - | XF ● |
| V000005 | Belt, timing HTD 5M-325-9 |  | SD 1.0● 1.2● | ZZ 1.0● 1.2● 1.5● | SFC ● | XF - |
| V000070 | Belt, timing HTD 5M-385-9 |  | SD - | ZZ 1.0- 1.5● | SFC - | XF - |
| V000074 | Belt, timing HTD 5M-415-9 |  | SD - | ZZ 1.0- 1.5● | SFC - | XF - |
| V000044 | Belt, timing HTD 5M-425-9 |  | SD - | ZZ 1.0● 1.2● 1.5- | SFC - | XF - |




spare part list

| | | | | | | |
|-------------|----------------------------|--|--------------------|----------------------------|----------|---------|
| V000075 | Belt, timing HTD 5M-475-9 |  | SD - | ZZ 1.0- 1.5● | SFC - | XF - |
| V000049 | Belt, timing HTD 5M-500-9 |  | SD - | ZZ 1.0- 1.2● 1.5- | SFC - | XF - |
| V000035 | Belt, timing HTD 5M-510-9 |  | SD - | ZZ 1.0● 1.2- 1.5- | SFC - | XF - |
| V000047 | Belt, timing HTD 5M-515-9 |  | SD 1.0- 1.2- | ZZ 1.0● 1.2● 1.5- | SFC - | XF - |
| V000097.575 | Belt, timing HTD 5M-575-15 |  | SD - | ZZ -- | SFC - | XF ● |
| V000029 | Belt, timing HTD 5M-630-9 |  | SD 1.0● 1.2● | ZZ 1.0● 1.2● 1.5● | SFC ● | XF - |
| V000097.975 | Belt, timing HTD 5M-975-15 |  | SD - | ZZ -- | SFC - | XF ● |




spare part list

| | | | | SD | ZZ | SFC | XF |
|--------------|----------------------------------|--|--|--------------------|--------------------|-----|----|
| V000098.1345 | Belt, transport 1345 |  | | - | - | - | ● |
| V000098.950 | Belt, transport 950 |  | | - | - | - | ● |
| V000082 | Bevel gear aligner tool |  | | - | - | ● | - |
| S000078 | Bevel gear drive assembly |  | | - | - | ● | - |
| I000005 | Bevel gear Ø10mm with keyway 3x3 |  | | SD 1.0● 1.2● | ZZ 1.0● 1.5● | ● | - |
| I000013 | Bevel gear Ø16mm with keyway 5x5 |  | | - | - | ● | - |
| E000003 | Controller, Conveylinx-Ai2 |  | | SD 1.0● 1.2● | ZZ 1.0● 1.5● | ● | ● |

spare part list

| | | | | | | |
|-------------|---------------------------|--|--------------------|----------------------------|----------|---------|
| E000004 | Controller, MotionLinx-Ai |  | SD 1.0● 1.2● | ZZ 1.0● 1.5● | SFC ● | XF ● |
| V000095 | Guide roller |  | SD - | ZZ - | SFC - | XF ● |
| I000004 | Logo cap |  | SD 1.0● 1.2● | ZZ 1.0● 1.2● 1.5● | SFC ● | XF - |
| E000005 | M12 inductive sensor |  | SD 1.0● 1.2● | ZZ 1.0● 1.5● | SFC ● | XF ● |
| E000039.700 | Motor for belt drive |  | SD - | ZZ - | SFC - | XF ● |
| E000039.850 | Motor for belt drive |  | SD - | ZZ - | SFC - | XF ● |
| E000001 | Motor, gear ratio: 11 |  | SD 1.0● 1.2● | ZZ 1.0● 1.5● | SFC - | XF - |


spare part list

| E000002 | Motor, gear ratio: 15 |  | SD 1.0● 1.2● | ZZ 1.0● 1.5● | SFC ● | XF - | |
|---------|---|--|--------------------|----------------------------|----------|---------|--|
| E000034 | Motor, gear ratio: 5 |  | SD - | ZZ - | SFC ● | XF - | |
| E000038 | Motor, gear ratio: 67 |  | SD - | ZZ - | SFC - | XF ● | |
| V000085 | Pillow block |  | SD - | ZZ - | SFC - | XF ● | |
| S000004 | Pulley drive assembly |  | SD 1.0● 1.2- | ZZ 1.0● 1.2● 1.5- | SFC - | XF - | |
| S000054 | Pulley drive assembly poly-V |  | SD 1.0- 1.2● | ZZ 1.0- 1.5● | SFC ● | XF - | |
| S000072 | Pulley drive assembly poly-V with bevel gear |  | SD - | ZZ - | SFC ● | XF - | |

spare part list

| | | | | | | |
|---------|--------------------------------|--|--------------------|----------------------------|----------|---------|
| S000023 | Tensioner element |  | SD 1.0● 1.2- | ZZ 1.0● 1.2- 1.5- | SFC - | XF - |
| S000027 | Tensioner element reversed |  | SD 1.0● 1.2- | ZZ 1.0● 1.2- 1.5- | SFC - | XF - |
| S000052 | Tensioner flat high |  | SD 1.0- 1.2● | ZZ 1.0- 1.2● 1.5● | SFC ● | XF - |
| S000058 | Tensioner flat high for ZigZag |  | SD - | ZZ 1.0- 1.2● 1.5- | SFC - | XF - |
| S000053 | Tensioner flat low |  | SD 1.0- 1.2● | ZZ 1.0- 1.2● 1.5● | SFC ● | XF - |
| S000050 | Tensioner poly-V High |  | SD 1.0- 1.2● | ZZ 1.0- 1.5● | SFC ● | XF - |
| S000051 | Tensioner poly-V Low |  | SD 1.0- 1.2● | ZZ 1.0- 1.5● | SFC ● | XF - |

spare part list

| | | | | | | |
|---------|--------------------------------|--|--------------------|----------------------------|----------|---------|
| S000003 | Wheel drive assembly |  | SD 1.0● 1.2● | ZZ 1.0● 1.5● | SFC ● | XF - |
| S000029 | Wheel drive assembly sensor |  | SD 1.0● 1.2● | ZZ 1.0● 1.5● | SFC ● | XF - |
| S000068 | ZigZag triangle assembly |  | SD - | ZZ 1.0- 1.5● | SFC - | XF - |
| S000035 | ZigZag triangle assembly left |  | SD - | ZZ 1.0● 1.2● 1.5- | SFC - | XF - |
| S000036 | ZigZag triangle assembly right |  | SD - | ZZ 1.0● 1.2● 1.5- | SFC - | XF - |

spare part list

Required quantity per machine – SLD & DLD

| | SLD 400 | SLD 600 | SLD 800 | SLD 1000 | DLD 400 | DLD 600 | DLD 800 | DLD 1000 |
|---------|------------|------------|------------|-------------|------------|------------|------------|-------------|
| E000001 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000002 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000003 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000004 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000005 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| I000004 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| I000005 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| S000003 | 1 | 2 | 3 | 4 | 2 | 4 | 6 | 8 |
| S000004 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| S000023 | 3 | 5 | 6 | 8 | 6 | 10 | 12 | 16 |
| S000027 | 1 | 1 | 2 | 2 | 2 | 2 | 4 | 4 |
| S000029 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| S000050 | 1 | 1 | 2 | 2 | 2 | 2 | 4 | 4 |
| S000051 | 1 | 2 | 2 | 3 | 2 | 4 | 4 | 6 |
| S000052 | 1 | 1 | 2 | 2 | 2 | 2 | 4 | 4 |
| S000053 | 1 | 2 | 2 | 3 | 2 | 4 | 4 | 6 |
| S000054 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| V000005 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| V000028 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| V000029 | 1 | 2 | 3 | 4 | 2 | 4 | 6 | 8 |
| V000035 | 1 | 2 | 3 | 4 | 2 | 4 | 6 | 8 |
| V000055 | 1 | 2 | 3 | 4 | 2 | 4 | 6 | 8 |
| V000056 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |

spare part list

Required quantity per machine - ZigZag

| | 400-2 | 600-2 | 800-2 | 1000-2 |
|---------|-------|-------|-------|--------|
| E000001 | 2 | 2 | 2 | 2 |
| E000002 | 2 | 2 | 2 | 2 |
| E000003 | 2 | 2 | 2 | 2 |
| E000004 | 2 | 2 | 2 | 2 |
| E000005 | 2 | 2 | 2 | 2 |
| I000004 | 3 | 5 | 7 | 9 |
| I000005 | 3 | 5 | 7 | 9 |
| S000003 | 1 | 3 | 5 | 7 |
| S000004 | 3 | 5 | 7 | 9 |
| S000023 | 6 | 9 | 12 | 15 |
| S000027 | 1 | 1 | 3 | 3 |
| S000029 | 2 | 2 | 2 | 2 |
| S000035 | 1 | 1 | 1 | 1 |
| S000036 | 1 | 1 | 1 | 1 |
| S000050 | 2 | 3 | 4 | 5 |
| S000051 | 1 | 2 | 3 | 4 |
| S000052 | 2 | 2 | 4 | 4 |
| S000053 | - | 2 | 2 | 4 |
| S000054 | 3 | 5 | 7 | 9 |
| S000058 | 1 | 2 | 4 | 6 |
| S000068 | 2 | 2 | 2 | 2 |
| V000005 | 1 | 1 | 1 | 1 |
| V000028 | 1 | 1 | 1 | 1 |
| V000029 | 1 | 3 | 5 | 7 |
| V000035 | 1 | 1 | 1 | 1 |
| V000044 | 2 | 2 | 2 | 2 |
| V000047 | 1 | 4 | 7 | 9 |
| V000049 | 1 | 1 | 1 | 1 |
| V000055 | 1 | 3 | 5 | 7 |
| V000056 | 2 | 2 | 2 | 2 |
| V000070 | 2 | 2 | 2 | 2 |
| V000074 | 1 | 1 | 1 | 1 |
| V000075 | 1 | 1 | 1 | 1 |
| V000076 | 1 | 2 | 2 | 2 |

spare part list

Required quantity per machine – Speed Flow Compact

| | SLD 400 | SLD 600 | SLD 800 | SLD 1000 | DLD 400 | DLD 600 | DLD 800 | DLD 1000 |
|---------|------------|------------|------------|-------------|------------|------------|------------|-------------|
| E000002 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000003 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000004 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000005 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| E000034 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| I000004 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| I000005 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| I000013 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| S000003 | 1 | 2 | 3 | 4 | 2 | 4 | 6 | 8 |
| S000004 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| S000029 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| S000050 | 1 | 1 | 2 | 2 | 2 | 2 | 4 | 4 |
| S000051 | 1 | 2 | 2 | 3 | 2 | 4 | 4 | 6 |
| S000052 | 1 | 1 | 2 | 2 | 2 | 2 | 4 | 4 |
| S000053 | 1 | 2 | 2 | 3 | 2 | 4 | 4 | 6 |
| S000054 | 2 | 3 | 4 | 5 | 4 | 6 | 8 | 10 |
| S000072 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| S000078 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| V000005 | 1 | 1 | 1 | 1 | 2 | 2 | 2 | 2 |
| V000029 | 1 | 2 | 3 | 4 | 2 | 4 | 6 | 8 |
| V000055 | 1 | 2 | 3 | 4 | 2 | 4 | 6 | 8 |
| V000082 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |

spare part list

| Required quantity per machine – X-Flow 90 | | |
|---|-----------------|-----------------|
| | X-Flow90 400 | X-Flow90 600 |
| S000093.400 | 1 | - |
| S000093.600 | - | 1 |
| V000098.950 | 1 | - |
| V000098.1345 | - | 1 |
| V000097.325 | 1 | 1 |
| V000097.575 | 1 | - |
| V000097.975 | - | 1 |
| V000085 | 2 | 2 |
| V000095 | 4 | 4 |
| E000039.700 | 1 | - |
| E000039.850 | - | 1 |
| E000038 | 1 | 1 |